

# SABRE 426

**MODEL YEAR 2012 OPTION PRICING** Price List #611S426

Issue 8/18/2011

ELECTRICAL	Part #	Revision
Replace standard batteries with Lifeline AGM	GE0039	
Additional AC or DC circuit breaker (specify amperage)	GE0002	
Clarion AM/FM/CD/MP3, satellite-ready stereo receiver with (4) speakers and remote control	GE0013	
Prewire for stereo and four speakers	GE0014	
Flat screen LCD TV and DVD player w/TV inlet and outlet	GE0051	
Hella Cabin Fan with breaker. Specify cabin	GE0004	
Additional Hella Cabin Fans (each). Specify cabins	GE0005	
Additional 12V outlet (specify location)	GE0003	
Xantrex Battery monitor	GE0034	
NAVIGATIONAL ELECTRONICS		
Grounding system for SSB radio (must be specified prior to molding)	GE0022	
ICOM VHF radio M504 w/antenna and flush mount kit	GE0015	
Raymarine ST70 Autopilot w/controls on cockpit coaming	GE0052	
Offset pedestal guard in lieu of standard	GD0011	
Angled pedestal guard in lieu of standard	GD0043	
MECHANICAL		
Reverse cycle air conditioning 16,000 BTU w/2nd shore cord	GM0014	
Additional 7,000 BTU air conditioner	GM0040	
4KW gen set installed in sail locker	GE0040	
Espar diesel heating system #D5-L	GM0017	
FIBERGLASS		
Light Hull color (other than Sabre white)	GH0003	
Dark Hull Color	GH0004	
Light deck color (other than Sabre white)	GD0001	
Contrasting anti-skid color (side deck, coach roof, cockpit)	GD0002	
KEEL CHOICES		
Shallow draft bulb/wing keel	GH0024	
PLUMBING		
Hot and cold transom shower	GM0006	
Salt water wash down system	GM0010	
Fresh water washdown in forward anchor locker	GM0036	
Tank Watch 4 for holding tank	GM0037	
Shorewater inlet to pressure water system	GM0018	
DECK AND EXTERIOR WOOD		
Lewmar V3 windlass w/rope chain gypsy	GD0005	
Pre-wire for 12 volt windlass	GD0006	
Cockpit Cushions - Tan. <u>Side seats only</u>	GD0017	
Laid teak cockpit coamings	GD0034	
Laid teak on transom step	GD0036	
Edson Cockpit table #761 for pedestal guard	GM0003	
Teak bang rail on topsides with stainless steel cap	GD0025	
RIGGING		
Navtec hydraulic backstay adjuster, split backstay	GR0010	
Selden Rigid Vang led aft	GR0055	
Prep for Inner forestay with running backstays	GR0044	
Flag halyard to mast head	GR0030	
Burgee halyard to spreader	GR0031	
SAIL HANDLING		
Furlex roller furling/w deck hardware	GR0056	
Prep for furling boom. Delete std boom, vang, reefing lines		
Self tacking jib system	GR0039	
Harken adjustable genoa car system	GR0041	
Additional Lewmar sheet stopper (ea)	GD0007	

Lewmar Electric Lewmar primary winches in lieu of standard	GD0016	
Lewmar Electric main halyard winch in lieu of standard	GD0029	
Spinnaker gear with Lewmar winches Harken adjustable genoa cars, Navtec Backstay adjuster, Hall Quik Vang and carbon fiber spinnaker pole	GR0013	
Aluminum spinnaker pole on mast. 2:1 controls. Lift aft to stopper	GR0053	
MPS/Spinnaker halyard led aft to stopper	GR0050	
Second genoa halyard led aft to cockpit w/stopper	GR0018	
Spinnaker pole topping lift led aft to stopper	GR0019	
Cunningham led aft	GR0042	
Spinnaker pole track on mast heel lift	GR0043	
<b>DECOR AND INTERIOR WOOD</b>		
Second head unit aft with aft facing chart table		
Ultrasuede fabric main salon only	GH0011	
Ultraleather fabric (main cabin only)	GH0036	
Corian counter in galley (with Corian sink covers)	GH0012	
Accord shades on opening and fixed ports	GH0020	

All prices are subject to change without notice and are not contractual

Standard yacht has a Sabre white hull and deck with cherry interior. See individual model specifications and equipment list for complete details. F.O.B. South Casco, Maine.

Sabre sailing yachts are covered by a LIMITED ONE YEAR WARRANTY. This warranty should be thoroughly reviewed by the customer before a purchase agreement is made. Please contact your dealer for details.

Sabre does not guaranty the durability of dark gelcoats. Hulls built with dark colors will fade more quickly than light colors, will show mold imperfections and scratches and can cause the laminate to post cure causing a cosmetic distortion of the surface. These deformations are not structural in nature and therefore are not covered by the Sabre Limited Warranty.